



FIG. 1



3/14




FIG. 4




FIG. 5

4/14




FIG. 6





FIG. 7

5/14



6/14

FIG. 8A





FIG. 8B

7/14



**FIG. 9B** 

FIG. 9A

8/14

FIG. 9A




FIG. 9B



9/14





FIG. 10

10/14


**SELECT UPPER POWER :**  
**5:00 U=07 L=05 M=02**



**SELECT**

FIG. 11

**SELECT LOWER POWER :**  
**5:00 U=07 L=05 M=02**



**SELECT**

FIG. 12

11/14




FIG. 13




FIG. 14

12/14




FIG. 15

13/14




FIG. 16

14/14




FIG. 17